

Fix My Street Ref:	Meeting Date	Minute Ref	Detail	By Whom	Due Date	Actions update	Revised Date	Status
4624046	11/05/2023	23.05.16	Blind 90° bend with no chevron markings or barriers This bend is on a very narrow road used by heavy farm vehicles and some delivery lorries as well as village traffic. The high hedge around Hemington House makes it impossible to see oncoming traffic from either direction. The bend is very steep and has no signs, markings or warnings. There has been an injury accident here. Chevron marking signs or similar should be installed.	Clerk	n/a	Status investigating - 2/6/23 Investigation: Ongoing - Thank you for your query. This will be investigated further and then a response made. No usual responses re progress - chase email sent to Highways Liaison 02/11/23 Response received advising that status is now 'Investigating' Update 02/05/24 - Investigation ongoing - passed to Community Liaison Team for investigation. 27/6/24 Investigation: Ongoing - Thank you for making your report we have now been able to consider your request. We will make a request to have a chevron sign installed in the location. Please be aware we are unable to give a timeframe for these works to be completed. 06/01/25 - Investigation: Completed (Highways to Monitor, Routine Inspection Programme) - Thank you for making your report we have now been able to consider your request. We will make a request to have a chevron sign installed in the location. Please be aware we are unable to give a timeframe for these works to be completed. This report will now be closed. 21/1/25 - Referred to Cllr Shacklock as 'Closed' when work not completed. Response via GS 31/1/25 - now with the Community Team: new works are managed through a different system, so removed from FixMyStreet. Hope to be able to commission works in 25/26 financial year, but space for chevrons is limited by narrow verges.		In-progress